

## Digital internal measuring instruments

Digital internal measuring instruments for measurements of bores, internal grooves and other hard-to-reach places.

- Measuring range: 5 - 60 mm.
- Resolution: 0.005 mm. Digital-analog display changes automatically between 0.01, 0.02 and 0.05 mm ( $\pm 20$  scale divisions).
- mm/inch conversion.
- ABS/INC switchable.
- Large LCD display, 340° rotatable.
- On/off switch.
- Automatic switch-off.
- Reset/preset.
- Hold and min/max functions.
- Adjustable tolerance limits.
- Measuring faces with different contact forms.
- Power supply: 1 battery type CR2032.



908.810



| Item No.             | Measuring range/mm | Accuracy mm | Length/mm |     |     | Contact form/mm     | Price EUR |
|----------------------|--------------------|-------------|-----------|-----|-----|---------------------|-----------|
|                      |                    |             | L         | A   | B   |                     |           |
| <b>Travel 10 mm:</b> |                    |             |           |     |     |                     |           |
| 908.810              | 5-15               | $\pm 0.02$  | 20        | 1   | 1.5 | ① R 0.3             |           |
| 908.811              | 10-20              | $\pm 0.02$  | 25        | 1.5 | 3.0 | ① R 0.3             |           |
| 908.812              | 20-30              | $\pm 0.02$  | 30        | 2   | 6.5 | ① R 0.5             |           |
| 908.813              | 30-40              | $\pm 0.02$  | 30        | 2.5 | 9.0 | ① R 0.5             |           |
| 908.814              | 40-50              | $\pm 0.02$  | 30        | 2.5 | 9.0 | ① R 0.5             |           |
| 908.816              | 10-20              | $\pm 0.02$  | 25        | 1.5 | 3.0 | ② $\varnothing 1.5$ |           |
| 908.817              | 20-30              | $\pm 0.02$  | 30        | 2   | 6.5 | ② $\varnothing 1.5$ |           |
| 908.818              | 30-40              | $\pm 0.02$  | 30        | 2.5 | 9.0 | ② $\varnothing 1.5$ |           |
| 908.819              | 40-50              | $\pm 0.02$  | 30        | 2.5 | 9.0 | ② $\varnothing 1.5$ |           |
| <b>Travel 20 mm:</b> |                    |             |           |     |     |                     |           |
| 908.820              | 5-25               | $\pm 0.03$  | 35        | 1   | 1.5 | ① R 0.3             |           |
| 908.821              | 10-30              | $\pm 0.03$  | 55        | 2   | 3.5 | ① R 0.5             |           |
| 908.822              | 20-40              | $\pm 0.03$  | 80        | 3   | 6.5 | ① R 0.5             |           |
| 908.823              | 30-50              | $\pm 0.03$  | 80        | 3   | 8.5 | ① R 0.5             |           |
| 908.824              | 40-60              | $\pm 0.03$  | 80        | 3   | 8.5 | ① R 0.5             |           |
| 908.826              | 10-30              | $\pm 0.03$  | 55        | 2   | 3.5 | ② $\varnothing 1.5$ |           |
| 908.827              | 20-40              | $\pm 0.03$  | 80        | 3   | 6.5 | ② $\varnothing 1.5$ |           |
| 908.828              | 30-50              | $\pm 0.03$  | 80        | 3   | 8.5 | ② $\varnothing 1.5$ |           |
| 908.829              | 40-60              | $\pm 0.03$  | 80        | 3   | 8.5 | ② $\varnothing 1.5$ |           |
| <b>Option:</b>       |                    |             |           |     |     |                     |           |
| 495.157              | Spare battery      |             |           |     |     |                     |           |

